

Aircraft for which Fokker Services have delivered CPDLC installation including a white annunciator in the flight deck

1. Affected Boeing 737 aircraft

1.1 Boeing 737-300 aircraft serial numbers:

23522, 23523, 23525, 23526, 23529, 23530, 23654, 23657, 23658, 23659, 23660, 23661, 23662, 23663, 23664, 23831, 23832, 24028, 24029, 24131, 24302, 24303, 24464, 25615, 25743, 27924, 28568, 28572, 28568, 28572, 28586, 28658, 28740, 29141, 29332

1.2 Boeing 737-400 aircraft serial numbers:

27834, 27914, 28752, 28753, 29001

1.3 Boeing 737-700 aircraft serial numbers:

30329, 30651, 33015, 35086

1.4 Boeing 737-800 aircraft serial numbers:

27980, 27982, 27986, 27987, 27989, 28070, 28177, 28213, 28220, 28229, 28231, 28375, 28385, 28531, 28821, 28822, 28826, 29036, 29037, 29681, 29991, 29921, 29923, 29925, 29926, 29932, 29933, 29934, 30231, 30276, 30278, 30421, 30680, 30692, 32243, 32365, 32366, 32367, 32368, 32604, 32905, 32906, 33022, 33079, 33559, 33561, 33812, 34252, 34253, 35082, 35092, 35093, 35106, 35850, 36529, 36813, 36881, 37747, 38012, 40696, 40697, 40723, 40728, 40871, 40876

2. Affected Boeing 757 aircraft

2.1 Boeing 757-200 aircraft serial numbers:

24014, 24015, 24016, 24122, 24135, 24136, 24397, 24793, 25488, 26635, 27973