Ministry of Civil Aviation Egyptian Civil Aviation Authority Airworthiness Engineering Directorate

DOC. 12130 Policy and Procedure Manual

Form 12130-111

Arab Republic of Egypt Ministry of Civil Aviation



Egyptian Civil Aviation Authority

Supplemental Type Certificate Validation

NUMBER: ECAA/AW/AE/M0037

This Certificate is issued to:

FOKKER SERVICES B.V.

Whose Business Address is:

HOEKSTEEN 40 2132 MS HOOFDDORP NETHERLANDS

Change Introduces ADS-B Out on the Boeing 737 clasic (B 737-300/-400/-500)

Original Product-Type Certificate Number: EASA.IM.A.120

Make: BOEING COMPANY

Model: B737-300/400/500

Original Supplemental Type Certificate Number: 10072602

Description of Type Design Changes:

Change Introduces ADS-B Out Capabilities on the Boeing 737 classic. The ATC Transponders will be changed and they will interface with the GNSS position source. The sensor may be a stand-alone sensor that is not coupled to the FMS.

Limitations and Conditions:

Piror to installation of this change/repair it must be determined that the interrelationship between this change/repair and any other previously installed change and / or repair will introduce no adverse effect upon the airworthiness of the product

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked or a termination date is otherwise established by the President of the Egyptian Civil **Aviation Authority**

Date of Application: 17/Dec./2021

Date of Issue

19-May-2022

Egyptian Civil Aviation Authority

Any Alteration of this Certificate is forbidden

This Certificate may be transferred if endorsed